



ENERGY SAVING SYSTEMS
2305A BADGER DR.
WAUKESHA, WI 53188
262-549-9337
WWW.ESSHVAC.COM

NEWLETTER- ISSUE 14
JANUARY 2006

PAST
2005 IS OFFICIALLY HISTORY. WE HOPE EVERYONE HAD A MERRY CHRISTMAS & A HAPPY NEW YEAR. 2005 HAD ITS SHARE OF CHALLENGES FOR ALL. RECORD AMOUNT OF HURRICANES, RECORD GAS PRICES, AND ENERGY PRICES COULD SEE A 50% INCREASE, IF I CONTINUED TO LIST THE REST; THIS NEWSLETTER COULD BE AS THICK AS WEBSTERS DICTIONARY. ON A HAPPY NOTE, THE SUMMER OF '05 WAS A BEAUTIFUL ONE. AS ALWAYS, WE THANK YOU FOR INTRUSTING YOUR HEALTH & COMFORT NEEDS TO ENERGY SAVING SYSTEMS. GOD BLESS IN 2006.

PRESENT
JANUARY 23, 2006. YOU MAY RECOGNIZE THAT DATE BECAUSE I'VE MENTIONED IT IN PREVIOUS NEWSLETTERS. THAT DATE ENDS THE MANUFACTURING OF ALL 10 SEER AIR CONDITIONERS. THE DEPARTMENT OF ENERGY IS MANDATING 13 SEER UNITS TO BE THE MINIMUM STANDARD. ALL MANUFACTURERS ARE RETOOLING THEIR PRODUCTION LINES TO PRODUCE THEIR NEW DESIGNS AVAILABLE FOR INSTALLATION AROUND MARCH 2006. THE GOOD NEWS, LESS ELECTRICAL CONSUMPTION DURING OPERATION. THE BAD NEWS, LARGER EQUIPMENT & HIGHER

COST. IF ANY LESSER EFFICIENCY EQUIPMENT IS IN STOCK, IT CAN BE INSTALLED, BUT THAT EQUIPMENT IS DWINDLING FAST. ANOTHER CHANGE THIS YEAR WILL BE CASH BACK INCENTIVES. FOCUS ON ENERGY, A WISCONSIN CASH BACK PROGRAM; WILL NOT BE GIVING ANY INCENTIVES ON 13 SEER MODELS, SINCE THIS IS NOW THE MINIMUM STANDARD. REWARDS WILL BE AVAILABLE ON HIGHER SEER MODELS. WE HAVE YET TO GET A DIFFINATIVE ANSWER ON FAILED COMPRESSOR REPLACEMENTS. SINCE SYSTEMS ARE DESIGNED TO WORK IN HARMONY, OUR QUESTION IS, "WILL 10 SEER COMPRESSORS BE AVAILABLE IF ONE FAILS, OR DO WE HAVE TO UPGRADE THE SYSTEM TO 13 SEER?" WHICH WOULD REQUIRE AN EVAPORATOR COIL CHANGE ALSO. STAY TUNED FOR MORE INFO.

THE LIGHTS ON!

NO, I'M NOT TALKING ABOUT SOMEONE LEAVING A ROOM & FORGETTING TO TURN OFF THE LIGHTS, I'M REFERRING TO ULTRAVIOLET LIGHTS. MANY OF YOU HAVE BEEN ENJOYING THE FRESH CLEAN AIR THAT UV LIGHTS CAN PRODUCE. OVER A ONE YEAR PERIOD OF CONSTANT PERFORMANCE, THE BULBS LOOSE THEIR INTENSITY, JUST LIKE GROW LIGHTS. THE BULBS MUST BE

REPLACED ANNUALLY TO ASSURE PROPER PERFORMANCE. THIS CAN BE DONE DURING ROUTINE MAINTENANCE CHECKS TO YOUR COMFORT SYSTEM, JUST INFORM US OF YOUR NEEDS BEFORE WE ARRIVE. DON'T HAVE A UV SYSTEM? CALL FOR MORE DETAILS!

WARRANTY VS MAINTENANCE

95% OF ALL REPLACEMENT FURNACES WE INSTALLED DURING 2005 WERE THE VARIABLE SPEED, 2 STAGE FIRING FURNACES. WHY SUCH A HIGH PERCENTAGE, YOU ASK? FIRST, IT IS THE BEST FURNACE ON THE MARKET TODAY. SECOND, THE 10 YEAR PARTS & LABOR WARRANTY. THIRD, THE CASH BACK REWARDS FROM BRYANT AND WI FOCUS ON ENERGY. THAT BRINGS ME BACK TO THE WARRANTY VS MAINTENANCE ISSUE. BRYANT REQUIRES ANNUAL MAINTENANCE BE PERFORMED TO THE EQUIPMENT TO ASSURE TOP PERFORMANCE & VALIDATION OF SERVICE IN THE EVENT OF A WARRANTY ISSUE. IF YOUR SYSTEM IS NEGLECTED FOR 2 TO 10 YEARS AND A PART FAILS, BRYANT MAY REQUEST FROM US PROOF OF ROUTINE MAINTENANCE. WE'D BE HAPPY TO SET UP THIS PROGRAM FOR YOU AT A REASONABLE COST.

COMFORT SOLUTIONS

DRY HOME? WITH MILDER WEATHER WE'RE NOT SEEING A BIG DEMAND FOR HUMIDIFIER INSTALLS, BUT WINTER ISN'T OVER YET!

DUSTY HOME? THE AIR SCREEN 1000 ELECTRONIC AIR CLEANER IS THE TICKET.

FINISHING THE BASEMENT? A CUSTOM ZONING SYSTEM INCORPORATED WITH YOUR EXISTING FURNACE OR BOILER.

DAMP HOME? EITHER A WHOLE HOUSE DEHUMIDIFIER OR A HEAT RECOVERY VENTILATOR.

NOISY FURNACE? BRYANTS QUIETEST VARIABLE SPEED FURNACE.

ALLERGIES/ASTHMA? ULTRA VIOLET LIGHT PURIFICATION. AS YOU SEE THERE ARE MANY OPTIONS AVAILABLE TO GIVE YOU THAT COMFORT YOU HAVE ALWAYS DREAMED OF.

BATTERIES!


USUALLY I MENTION THIS IN THE FALL, MANY THERMOSTATS, SMOKE DETECTORS & CARBON MONOXIDE ALARMS RUN ON BATTERIES. DID YOU CHANGE YOURS? IF NOT, PLEASE, DO SO TODAY.

HIGH GAS BILL?

YOU PROBABLY SAID THE SAME WORDS THAT I DID WHEN I OPENED MY LAST GAS & ELECTRIC BILL, "WHAT THE (FILL IN THE BLANK)". ALL THOUGH IT SHOULD NOT HAVE BEEN A SHOCK BECAUSE I KNEW WHAT WAS COMING. BUT, HEY, JUST A NORMAL ALL AMERICAN RESPONSE. HOPEFULLY THE NATIONAL WEATHER SERVICE IS CORRECT IN PREDICTING AN ABOVE AVERAGE TEMPERATURE FOR OUR REGION. JANUARY HAS PROVED THAT SO FAR, IT WILL HELP TO KEEP THE NEXT BILL IN CHECK, I HOPE!

TIPS

CHANGE OR CHECK THAT AIR FILTER REGULARLY. LOWER THE THERMOSTAT 1 OR 2 DEGREES. BUY A PROGRAMMABLE STAT IF YOU DON'T ALREADY HAVE ONE. IF YOU DO, INCREASE THE OFF CYCLE DEGREES EVEN MORE. OPEN WINDOW TREATMENTS AND SHADES- LET THAT SUN SHINE IN! OH, THAT'S RIGHT, WHAT SUN? CHECK ATTIC INSULATION & ADD MORE IF FEASIBLE. HOW ABOUT THOSE SILL JOIST SPACES IN THE BASEMENT, ARE THEY INSULATED? FOAM SHUT GAPS OR HOLES AROUND THE FOUNDATION, GAPS AROUND PLUMBING OR ELECTRICAL MATERIAL THAT RISES VERTICALLY UP WALLS. "GREAT STUFF" WORKS WELL FOR THIS. REMEMBER TO ALWAYS READ SAFETY AND WARNING LABELS BEFORE USING ANY PRODUCT.



\$\$\$ COUPONS \$\$\$

SECOND WIND MODEL 2000 UV LIGHT
\$549.00 INSTALLED
EXPIRES 3-31-06
AIR SCREEN 1000 ELECTRONIC AIR CLEANER
\$275.00 INSTALLED
EXPIRES 3-31-06
10% OFF ANY AIR FILTER
EXPIRES 3-31-06
HONEYWELL HUMIDIFER MODEL HE225
\$349.00 INSTALLED
EXPIRES 3-31-06



Energy Saving Systems